

TRACKING EXAMPLE A



DANGEROUS MONITOR ST (OR MONITORING DEVICE)

↑
OUT DAW INTO
MONITOR ST
INPUT 1

←
OUT MONITOR 1&2 OF
LIAISON INTO MONITOR ST
INPUT 2&4*
(PRE&POST BUSS A)

COMPUTER INTERFACE (DAW/CONVERTER)

←
OUT BUSS A
OF LIAISON
INTO DAW

MIC PREAMP

↓
OUT PREAMP INTO
BUSS A OF LIAISON

*Utilizing input 4 on the MONITOR ST, allows the post processing level to be reduced, thus matching it to the original for true A/B comparisons.

